

1/5

FIG 1






FIG 2





3/5

FIG 4





FIG 5A

Start: CLK=0 & Q=0



4/5

FIG 5B




FIG 5C




FIG 5D




FIG 5E




FIG 6

